

FRIT DIVISION

CLEVELAND - NASHVILLE - LOS ANGELES

## MATERIAL SAFETY DATA SHEET

SECTION I									
MANUFACTURER'S NAME Ferro Corporation  EMERGENCY TELEPHONE NO. 216/641-8580									
ADDRESS (Number, Street, City, State, and ZIP Code)									
4150 E. 56th. Street Cleveland, Ohio 44105 CHEMICAL NAME AND SYNONYMS TRADE NAME AND SYNONYMS									
CHEMICAL FAMILY FORMULA									
Blue Epoxy Paste Complex Mixture									
SECTION II HAZARDOUS INGREDIENTS									
PAINTS, PRESERVATIVES, & SOLVENTS	*	TLV (Units)	ALLOYS AND METALLIC COATINGS	5	TLV (Units)				
PIGMENTS N/A	T ,		BASE METAL	_	10				
CATALYST			ALLOYS						
VEHICLE Non-Toxic •			METALLIC COATINGS						
SOLVENTS			FILLER METAL PLUS COATING OR COME FLUX						
ADDITIVES			OTHERS						
OTHERS				-					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES									
. HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GASES %									
N/A									
•									
SECTION III PHYSICAL DATA									
BOILING POINT (F.)	1 4	above 100	SPECIFIC GRAVITY (HZ0=1)	>1	.0				
VAPOR PRESSURE (mm Hg.)	Les	s than	PERCENT VOLATILE BY VOLUME (%)		0				
VAPOR DENSITY (AIR=1)	N	1/A	EVAPORATION RATE		N/A				
SOLUBILITY IN WATER	No	one	- 1	<del>- </del>	.,,				
APPEARANCE AND ODOR Viscous Paste - Low Odor									
Table Bow Odol									
SECTION IV FIRE AND EXPLOSION HAZARD DATA									
FLASH POINT (Method used) 450°F (open			FLAMMABLE LIMITS Lei		Uoi				
EXTINGUISHING MEDIA									

None - CO and CO2 are products of combustion.

SPECIAL FIRE FIGHTING PROCEDURES

UNUSUAL FIRE AND EXPLOSION HAZARDS

None

· //		<del></del>						
		SECTION	V HEA	D DRASAN HTJ	ATA			
THRESHOLD LIMIT V	ALUE							
EFFECTS OF OVEREX	Posure Prolon	ged cont	act ca	n cause ski	n irritation. Mild irritant			
in direct contact with eyes.								
EMERGENCY AND FIRST AID PROCEDURES  Wash skin with soap and water. Flush eyes with								
water 10-	20 minutes.							
CTABLITY	<del></del>	SECTION		EACTIVITY DAT	Α			
STABILITY	UNSTABLE							
	STABLE	χ						
INCOMPATABILITY (Materials to avoid)  HAZARDOUS DECOMPOSITION PRODUCTS								
	- I		· <del>,                                     </del>	_				
HAZARDOUS POLYMERIZATION	MAY OCCUR	MAY OCCUR		CONDITIONS TO	With amines, bases,			
	WILL NOT OC	CUR	<u> </u>	<u> </u>	acids, polyamids,			
	,		· · · · · · · · · · · · · · · · · · ·					
SECTION VII SPILL OR LEAK PROCEDURES								
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Prevent contact with amines, polyamids, etc. Wipe with solvent rags and								
discard - soak up with sawdust or sweeping compound and discard.								
·		·	· · · · · · · · · · · · · · · · · · ·					
WASTE DISPOSAL MET	Can be	inciner	rated.					
•	•							
<u></u>								
	SECTION	VIII SP	ECIAL P	ROTECTION IN	FORMATION			
RESPIRATORY PROTECTION (Specify type)  None required								
VENTILATION	LOCAL EXHAUST	Yes	<u>vqurro</u>	SPECIAL				
	MECHANICAL (General)				OTHER			
PROTECTIVE GLOVES	Yes			EYE PROTECTION	0-5-1			
OTHER PROTECTIVE E	QUIPMENT	Safety glasses or goggles						
Aprons, Creams								
SECTION IX SPECIAL PRECAUTIONS								
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Store'in sealed containers in dry, cool								
(75 <sup>0</sup> ) area.	<del></del>	<del></del> -	3 COT	e TH Sealed	containers in dry, cool			
OTHER PRECAUTIONS			<del></del>	<del> </del>				
		····						

<sup>&</sup>quot;The information herein is given in good faith but no warranty, epress or implied, is made".